

ChinaCNCzone

Engrave your colorful life !

6090 mini Numerical Control Carving Machine manual -Mach3 version

Shenzhen Scotle Technology Group Limited
Chinacnczone

Address: 038-068 2F Handmade Culture Street, Phase III,
Shuik Road, Bantian, Longgang, Shenzhen, China

Website: www.chinacnczone.com

www.scotle.en.alibaba.com

Email: sales@scotle.com

sales@chinacnczone.com

Tel: 0755-89378482

Content

Outline.....	3
PC selection and port installation.....	3
Machine's parameters.....	4
Highlights for this CNC 6090.....	5
Mach3 controller introduction.....	5
How to install the step motors in 6090 mini CNC?.....	6
Software Instillation.....	6
Software Data Setup.....	7
Testing.....	13
Work-piece Placement and Tool-setting Method.....	14
Common Faults and Maintenance of NC Carving machine Common faults.....	15
Daily maintenance.....	17

Outline

Chinacnczone 6090 mini CNC is a kind of small-size product mainly applied in the processing and manufacture of woodworking, advertising, modeling and art ware, particularly appropriate to the carving of the materials such as wood, plastics, acrylic and soft metal as aluminum and copper.

Mach3 CNC control software is an numerical control system developed by ArtSoft based on the Windows as its platform. The new-type of numerical control system which is characterized by simple operation and maintenance, openness, stable performance and low price is a full-functional CNC controller transformed from the standard PC. With its max. 6-axis interlock CNC, it supports input of various file formats such as DXF, BMP, JPG, and HPGL and immediately generates G code displayed by the sight G code. It is controlled by spindle-speed control with multiple relay through hand-held pulse including large quantities of machining strategies and video display. With its digitized touch screen, with full-screen display, the tracking, automatic tool-setting and the routine light-flooding execution (break-point memory) can be achieved.

The system has the functions such as thread pitch error compensation, backlash compensation, length compensation and tool nose radius compensation and wear compensation.

The axial motion acceleration and speed adjustment interface can be adjusted according to the demand to adapt to the high-speed and high-precision processing.

PC selection and port installation

1. You must have a desktop with parallel port.
2. The desktop should meet the following requirements: CPU/1GB, internal storage of 512, hard disk capacity of more than 20G, parallel port, Win XP.



Machine's parameters



Effective working travel	580(X)mm*880(Y)mm*85(Z)mm	
Work table dimension	600mm*900 mm	
Frame materials	aluminum alloy 6063 and 6061 the unique and dedicated mold extrusion profiles. let counterfeiter's dwarfs	
acceptable material thickness	≤100mm	
Driving units	X/Y/Z axis	1605 ballscrew
Sliding units	X axis	Dia.16mm chrome plate shafts
	Y axis	Dia.20mm chrome plate shafts
	Z axis	Dia.13mm chrome plate shafts
Stepping motor type	57 two-phase 3A 150N.cm	
Spindle motor	Brand new 1500W water cooling spindle, 24000RPM	
Principal axis collet	ER20/3.175 mm/6mm	
Repeat accuracy	0.05mm	
Spindle precision	radial beat acuities 0.03 mm	
Software environment	Windows xp, Windows 7	
Maximum speed	0-4000mm/min	
Control unit	Toroidal transformer + PWM power supply module + TB6560 3axis drive board	
Computer connection	25 pins parallel port	
Command code and software	G code	
Protection	Emergency stop button	
Operating Voltage	AC220V AC110V will provide voltage changer	

Highlights for this CNC 6090

1. 2200W Water Cooled Spindle
2. With live video support
3. Ball screw high precision
4. Independent power supply for main board, prolong using life
5. Mach 3 software is simple and intelligent, can be connected with computer
6. Limited switch added
7. Auto-Checking function
8. With 4 axis, can engrave cylinder object

This 4 Axis CNC 6090 can be widely used

A. Widely used not only for Aluminum but also acrylic, brass, wood, PVC, PCB and so on

B. Ideal for milling, engraving, drilling & routing.

C. For Industry, Technology Research, Advertising Design, Arts Creation, Teaching, Student Project and Hobby Purposes, Building Model Making, Advertising Signs, Artwork, Crafts, Aircraft Models, RC Model parts.

Mach3 controller introduction





How to install the step motors in 6090 mini CNC?

Below video link in You-tube show you the correct way and steps of install the step motors in Chinaacnczone 6090 mini CNC.


<https://youtu.be/2r3mgSo3UoQ>

Software Instillation


Firstly, open the disk and find Mach3versionR3.041.exe in the file of mach3, open it and install it.

Mach3VersionR3.041.exe	2011/5/24 21:21	应用程序	25,733 KB
------------------------	-----------------	------	-----------


After installation, click on “Finish” to complete the setup.




Open the “Parameter settings” file folder, and copy the files in it under the installation directory of Mach3.




Software Data Setup


Open the MACH3 installed  , click on “” in the menu and select successively metric/English system and click on “确定” to confirm your selection.




Enter “set default unit” and select MM’s or Inches. In most cases, MM’s.




Click on “config” in the menu and select successively port/kernel speed, port setting and axis selection.




Pay attention that each PC has a different PortAddress. You need to modify it to your own address of the PCI.



To check the port address, click the right-hand button of “my computer” and select “manage”. Then enter device manager, find your port of PCI, click the right-hand button of “properties” and enter “resource” to check.




Click on “motor outputs” again. And the setup process is as follows. Pay attention if you have AxisA, you should select AAxis. If no, leave it there.




Click on “Motor outputs” according to the chart display settings
Then the first point of application re-election confirmed

Click “input Signals” and the setup process is as follows.




Click on “Input Signals” by setting the figure shows,
Then point the application

Click “output Signals” again and the setup process is as follows.




Click “Output Signals”, then point the application


When the setup is over, click “确定” to confirm the operation.




Click “config” in the menu again, and enter “Motor turning” and execute the setup. Pay attention that the setup of X and y axis is the same. After the setup, click on “SaveAxis Settings”.




The click on Z Axis and the setup process is as follows.




The click on the principal axis and the setup process is as follows. After the setups are over, click on “OK”.






Click “config” in the menu again and enter successively “general config” and the setup process is as follows.



Click again on “config” in the menu and enter successively “Safe_Z Setup”. The setup process is as follows.




The setup is completed...

Testing


pgup Key {Axis Z turn forward to +} pgdn Key {Axis Z turn reversely to -}

After the setup, test if each direction is correct and the motion directions of Axis X, Y, and Z. Click on “arrow up” on the keyboard {Axis turn forward to Y +}, “arrow down” {Axis Y turn reversely to -}, “arrow left” {Axis X turn forward to +} and “arrow right” {Axis turn reversely to -}.

And click on “pgup” {Axis Z turn forward to +} and “pgdn” {Axis Z turn to -}



Test the operation of the spindle and input a spindle speed and click on “enter” and then click on “spindle CW F5”.




Work-piece Placement and Tool-setting Method

Work-piece placement



Installation instruction of the pressing plate



In the chart below, each of the axis should be zero clearing, then make the spindle touch X+ first and then X-. Calculate the distance between X+ and X-, divided by 2 and the result is the central point of X. Input the result in Axis X.



Pay attention that Axis Y is the same operation and Axis Z will be zero clearing when touching the surface of the workpiece. If you have any questions about the too-setting, watch the video for the instructions.

Common Faults and Maintenance of NC Carving machine

Common faults

I. Uncontrollable Axis Z

1. Loose control card or fault in the control card;
2. Electrostatic interference;
3. Failure in the motor wire of axis Z;
4. Wrong file path;
5. Converter interference;
6. Problem or virus in the computer system;
7. Mis-operation

II. Errors

1. Loose control card or fault in the control card;
2. Failure in the driver;
3. Failure in the stepping motor;
4. Electrostatic interference;
5. Failure in the motor wire;
6. Failure in the data line;
7. Wrong path;
8. Loose coupling or rupture in the coupling;
9. Too rapid processing speed;
10. Problem or virus in the computer system

III. Regular carving

1. Loose control card or fault in the control card
2. Failure in the stepping motor

3. Failure in the driver or inconsistent settings of electricity subdivision and software

4. Failure in the motor wire of Axis Z;
5. Motor fault of spindle
6. Converter interference or wrong data setting
7. Electrostatic interference;
8. Problem or virus in the computer system

IV . Uncontrollable carving machine

1. Fault in the control card;
2. Converter interference;
3. Wrong file path
4. Electrostatic interference;
5. Problem in the software setup;
6. Failure in the driver or wrong electricity subdivision setup;
7. Failure in data line;
8. Problem or virus in the computer system

V. Uneven milling bottom

1. Out of plumb of the spindle and the table-board;
2. Problem in the tool;
3. Problem in the control card;
4. Problem in the driver of Axis Z

VI. Spindle off

1. Internal short of the spindle;
2. Electricity shielding;
3. Wrong setting of the parameter of the frequency converter;
4. Fault in the control card;
5. Spindle short or data line short

VII . Abnormal sound of the spindle

1. Fault in the setting of the frequency converter;
2. Spindle off;
3. The problem of the spindle

VIII . Opposite Direction of Motion or Back to Mechanical Origin

1. Alter the file in the wordpad;
2. Alteration of the connection method of the frequency converter;
3. The direction of roll out in the software

IX . Unable to Return to Mechanical origin

1. Opposite direction;
2. Loose control card or fault in the control card;
3. Fault in the limit switch or data line;
4. Failure in the driver;
5. Failure in the stepping motor

X . Incontrollable Spindle

1. Fault in the control card;
2. Failure in the frequency converter

XI . Error Prompt of “Failure in Read the Card, Please Check”

1. Check if the driver of the board card is installed correctly or change a PCI slot for the board card;
2. Re install the two data connecting lines and check if the needle is broken;
3. Replace the board card if it is its problem.

Daily maintenance

1. The machine should be placed in a dry and well-ventilated place (avoid long time exposure in the sun)
2. The machine must be configured with a reliable voltage stabilizer to ensure safe earthing of the ground electrode.
3. Try to avoid using the PC with internet access to output the file to the carving machine.
4. Maintain the machine once every month (paint appropriate amount of lubricating oil on the lead screw)
5. The control cabinet should be placed in a well-ventilated place and avoid the operation in the high-temperature area.
6. Check if the circuit of the carving machine is loose regularly.
7. Don't place stuffs (like magnetic materials, dead weight cargo and liquid) on the drilling crew or nose of the carving machine.
8. Don't keep the machine working in the same corner in a long time (to avoid the unsuccessful lubrication due to the failure of contacting of the lead screw and guide rail with the cross member for a long time)
9. Keep the lubrication in the good state by regular checking, cleaning the lead screw, and adding or changing the grease or oil in order to remain the moving parts such as the lead screw and cross member lubricated and thus reduce the rate of wear of the machine.